

WV100039



Fire-resistant, scratch-resistant, and anti-fog polycarbonate eye protection. Requires KASK Easy Click Adapters FR. Can be worn with corrective glasses.

Compatible with KASK Zenith X, Primero and Quantum helmet series.

The ZEN PLUS VISOR mounted on the QUANTUM helmet, via the EASY CLICK ADAPTERS FR, makes the helmet usable for use in wildland firefighting (EN16471) and technical rescue activities (EN16473) where there is potential exposure to flames.

MOUNTING PARTS



TECHNICAL DETAILS

 <p>STANDARD EN ISO 16321 EN 14458</p> <p>CE 2754</p> <hr/> <p>ANSI Z87.1</p>	 <p>CATEGORY III</p>  <p>ENHANCED OPTICAL PERFORMANCE 1</p>	 <p>MATERIAL Polycarbonate</p>  <p>WEIGHT 80 g</p>
---	--	---

TECHNOLOGIES

 <p>PANORAMIC LENS Developed to maximize visibility with minimal viewing distortion.</p>	 <p>COMPATIBLE WITH GLASSES Designed for use over corrective glasses.</p>
 <p>ANTI-FOG Equipped with an anti-fog treatment to increase wearer visibility when active and in a variety of conditions.</p>	 <p>DRIP PROOF UPPER CONTOUR Rubber edge protects eyes from liquid and debris from entering the visor.</p>
 <p>ABRASION AND SCRATCH RESISTANCE Lens treatment designed with protection from abrasion and scratches or increased durability and viewing clarity.</p>	 <p>EASY CLICK ADAPTERS Adapters designed to be easily attached and removed to KASK eye and face protection accessories.</p>

CE MARKINGS

CODE	COLOR	MARKING
WV100039-500	CLEAR	CE 2754 EN14458:2018 KASK ZEN PLUS MM/YY = ⊙ BT E1/E3 2C-1,2 -30°C +50°C ☐
WV100039-510	SMOKE	CE 2754 EN14458:2018 KASK ZEN PLUS MM/YY = ⊙ BT E1/E3 5-1,4 -30°C +50°C ☐
WV100039-520	SILVER MIRROR	CE 2754 EN14458:2018 KASK ZEN PLUS MM/YY = ⊙ BT E1/E3 5-2,5 -30°C +50°C ☐

ANSI MARKINGS

CODE	COLOR	MARKING
WV100039-500	CLEAR	ANSI Z87 + U6 X D3
WV100039-510	SMOKE	ANSI Z87 + U6 L1.5 X D3
WV100039-520	SILVER MIRROR	ANSI Z87 + U6 L2 X D3

ADDITIONAL INFORMATION

GUARANTEE
3 years starting from the date of purchase.

LIFE SPAN
10 years starting from the date of manufacture. Life span depends on various factors that can cause deterioration such as sudden temperature changes, the amount of exposure to direct sunlight and the intensity of use. Altered vision and scratches are elements that signal the need to check for deterioration of the visor.

CLEANING
Clean only with water and mild soap. Allow to air dry. Do not use chemical detergents, solvents, petrol powders as they are too aggressive and could lower the structural resistance of the visor.

3
YEARS
GUARANTEE

10
YEARS
LIFE SPAN

SCAN FOR COMPLETE COLLECTION