WVI00037



Scratch-resistant and anti-fog polycarbonate full face protection. Available in 3 lens color options for various levels of light transmission. Flips up and down. Screw set for mounting is included with visor. Can be worn with corrective glasses.

Compatible with KASK Superplasma helmet series.

#### **MOUNTING PARTS**



## **TECHNICAL DETAILS**



**STANDARD** EN ISO 16321



ANSI Z87.1



CATEGORY





MATERIAL

Polycarbonate
WEIGHT



**WEIGH** 120 g



**LENGTH** 190 mm

## **TECHNOLOGIES**



#### **ANTI-FOG**

Equipped with an anti-fog treatment to increase wearer visibility when active and in a variety of conditions.



### ABRASION AND SCRATCH RESISTANCE

Lens treatment designed with protection from abrasion and scratches or increased durability and viewing clarity.



# DRIP PROOF UPPER CONTOUR

**COMPATIBLE WITH GLASSES** 

Designed for use over corrective glasses.

Rubber edge protects eyes from liquid and debris from entering



### **PANORAMIC LENS**

Developed to maximize visibility with minimal viewing distortion.

## **CE MARKINGS**

CODE	COLOR	MARKING
WVI00037-500	CLEAR	V2 FULL FACE   MM/YY   C E   KA/K   UL1,2   ET   -5°C +55°C   K   N   CH   9
		16321   <b>K \ / K</b>   ET   1-M/1-L   -5°C +55°C   6   CH   9
WVI00037-510	SMOKE	V2 FULL FACE   MM/YY   <b>C E   K \ / K</b>   GL2   ET   -5°C +55°C   K   N   CH   9
		16321   <b>K//K</b>   ET   1-M/1-L   -5°C +55°C   6   CH   9
WVI00037-520	SILVER	V2 FULL FACE   MM/YY   <b>C E   K \ / K</b>   GL1   ET   -5°C +55°C   K   N   CH   9
	MIRROR	16321   <b>KA/K</b>   ET   1-M/1-L   -5°C +55°C   6   CH   9

## **ANSI MARKINGS**

CODE	COLOR	MARKING
WVI00037-500	CLEAR	ANSI Z87   +   U6   X   D3
WVI00037-510	SMOKE	ANSI Z87   +   U6   L2   X   D3
WVI00037-520	SILVER MIRROR	ANSI Z87   +   U6   L2   X   D3

## **ADDITIONAL INFORMATION**

## GUARANTEE

3 years starting from the date of purchase.

#### LIFE SPAN

10 years starting from the date of manufacture. Life span depends on various factors that can cause deterioration such as sudden temperature changes, the amount of exposure to direct sunlight and the intensity of use. Altered vision and scratches are elements that signal the need to check for deterioration of the visor.

#### CLEANING

Clean only with water and mild soap. Allow to air dry. Do not use chemical detergents, solvents, petrol powders as they are too aggressive and could lower the structural resistance of the visor.

3 YEARS GUARANTEE

10 YEARS LIFE SPAN



SCAN FOR COMPLETE COLLECTION











